

Conditions of Fukushima Dai-ichi Nuclear Power Station Unit 1 (As of 11:00 March 24th, 2011)



Conditions of Fukushima Dai-ichi Nuclear Power Station Unit 2

(As of 11:00 March 24th, 2011)



Major Events after the earthquake

11th 14:46 Under operation,

Automatic shutdown by the earthquake

11th 15:42 Report based on the Article 10 (Total loss of A/C power)

11th 16:36 Occurrence of the Article 15 event (Inability of water injection of the Emergency Core Cooling System)

13th 11:00 Started to vent

14th 13:25 Occurrence of the Article 15 event (Loss of reactor cooling functions)

14th 16:34 Started to inject water to the Reactor

14th 22:50 Occurrence of the Article 15 event (Unusual rise of the pressure in PCV)

15th 0:02 Started to vent

15th 6:10 Sound of explosion

15th around 6:20 Possible damage of the suppression chamber

20th 15:05~17:20 Approximately 40 ton seawater injection to the Spent Fuel Pool (SFP) via Fuel Pool Cooling System (FPC) 20th 15:46 Power Center received electricity.

21st 18:22 White smoke generated. The smoke died down and almost invisible at 07:11 March 22nd.

22nd 16:07 Injection of around 18 tons of seawater to the Spent Fuel Pool


Current Conditions: Water is being injected to Spent Fuel Pool and seawater is being injected to the core


*3 Primary Containment Vessel *4 Suppression Pool

*1 Residual Heat Removal System
*2 Emergency Diesel Generator

(Editorial committee for Nuclear Energy Handbook, Nuclear Energy Handbook)

Conditions of Fukushima Dai-ichi Nuclear Power Station Unit 3





Major Events after the earthquake

11th 14:46 Under operation,

Automatic shutdown by the earthquake

11th 5:42 Report based on the Article 10 (Total loss of A/C power)

20:41 Started to vent

13th 5:10 Occurrence of the Article 15 event (Inability of water injection of the Emergency Core Cooling System)

13th 9:20 Started to vent

13th 13:12 Started to inject seawater and borated water to

14th 5:20 Started to vent

14th 7:44 Occurrence of the Article 15 event (Unusual rise of the pressure in PCV

14th 11:01 Sound of explosion

c

17th 9:48 ~ 10:01 Water discharge by the helicopters of 16th around 8:30 White smoke generated

Self-Defense Force (4 times)

pressure water-cannon trucks (Police: once, Self-Defense Force: 5 times 19:05 ~ 20:07 Water spray from the ground by High

18th before 14:00 ~ 14:38 Water spray from the ground by 6 fire engines of Self-Defense Force

of the US Military ~14:45 Water spray from the ground by a fire engine

19th 14:10 ~ 20th 3:40 Water spray by Tokyo Fire 19th 0:00 ∼01:00 Water spray by Tokyo Fire Department

Department

20th 11:00 Pressure of PCV rose(320kPa). Afterward fell $20^{\text{th}} 20:39 \sim 21^{\text{st}} 3:58 \text{ Water spray by Tokyo Fire}$

Department

21st about 15:55 Grayish smoke generated and was confirmed to be died down at 17:55.

22nd 15:10 ∼15:59 Water spray by Tokyo Fire Department 22nd 22:43 Lightening in the Central Control Room was

recovered.

 23^{rd} 11:03 \sim 13:20 Injection of about 35ton of sea water to the Spent Fuel Pool (SFP) via the Cooling and

Purification Line (FPC)

24th 5:35 Injection of sea water to SFP via FPC 23rd around 16:20 Black smoke generated and was confirmed to died down at around 23:30 and 24th 4:50


(12:08 Confirmed the injection of $4^{\sim}5t/h$)

Current Conditions: Water spray to Spent Fuel Pool and sea water injection to

*4 Suppression Pool

Conditions of Fukushima Dai-ichi Nuclear Power Station Unit 4





earthquake

earthquake

In periodic inspection outage when the earthquake occurred.

11th 15:42 Report based on the Article 10 (Total loss of A/C power)

14th 4:08 Water temperature in the Spent Fuel Pool, 84°C

15th 6:14 Partial damage of wall in the 4th floor confirmed

15th 9:38 Fire occurred in the 3rd floor.

(12:25 extinguished)

16th 5:45 Fire occurred. TEPCO couldn't confirm any fire on the ground. (6:15) 20th 8:21~9:40 Water spray over the Spent Fuel Pool by Self-Defense Force

20th around 18:30~19:46 Water spray over the Spent Fuel Pool by Self-Defense Force 21st 6:37~8:41 Water spray over the Spent Fuel Pool by Self-Defense Force

21st about 15:00 Work for laying cable to Power Center was completed.

22nd 10:35 Power Center received electricity 22nd 17:17 ~ 20:32 Water spray by Concrete Pump Track


23rd 10:00∼13:02 Water spray by Concrete Pump Track

Current Conditions: No fuel is in RPV*3. Water spray to Spent Fuel Pool

(Editorial committee for Nuclear Energy Handbook, Nuclear Energy Handbook)

*1 Residual Heat Removal System
*2 Emergency Diesel Generator
*3 Reactor Pressure Vessel

Conditions of Fukushima Dai-ichi Nuclear Power Station Unit 5 (As of 11:00 March 24th, 2011)



Conditions of Fukushima Dai-ichi Nuclear Power Station Unit 6 (As of 11:00 March 24th, 2011)

